TSGS#16(02)0282

Technical Specification Group Services and System Aspects Meeting #16, Marco Island, Florida, 10-13 June 2002

Source: SA5 (Telecom Management)

Title: Rel-4 CR 32.111-3 (Fault Management; Part 3: Alarm Integration

Reference Point: CORBA SS) Addition of 'indeterminate' probable

cause in IDL definition

Document for: Approval

Agenda Item: 7.5.3

Doc-1 st	Spec	Spec CR R Phase			Subject	Cat	Ver	Ver	Doc-2 nd	Workitem
-Level							Cur	New	-Level	
SP-020282	32.111-3	016	-	Rel-4	Addition of 'indeterminate' probable cause in IDL definition	F	4.2.0	4.3.0	S5-026239	OAM-FM

Meeting #28, Sophia Antipolis, FRANCE, 20 - 24 May 2002												
CHANGE REQUEST										CR-Form-v5		
*	32.	111-3	CR	016	3	≋ rev	-	ж	Current vers	sion:	4.2.0	*
For <u>HELP</u> on using this form, see bottom of this page or look at the pop-up text over the % symbols.												
Proposed chang	e affe	ects: #	(U)	SIM	ME/	UE	Rad	io Ac	cess Networ	k X	Core N	etwork X
Title:	₩ A	ddition	of 'inde	terminate	e' proba	able cau	ıse in	IDL	definition			
Source:	ж S	A5										
Work item code:	ж <mark>С</mark>	AM-FM							Date: ₩	24	05/2002	
Category:	De	se <u>one</u> of F (con A (con B (ad C (fur D (ed	rrection) rrespondition of actional itorial m planatic	owing cated as to a confection of the confection of the FR 21.900	rrection on of fea n) above o	in an ea ature)		elease	Release: # Use <u>one</u> or 2 e) R96 R97 R98 R99 REL-4 REL-5	f the for (GSI) (Relea (Relea (Relea (Relea)))
December of		DO The	(: d a t a	in ata!	ما م ما مید م	da aayya	a :a .a	. ! !				
Reason for chan Summary of cha	_	≆ Add r		probable						leCau	use interfa	ıce, in
Consequences in not approved:	f :								RBA Solution comments" b) and
Clauses affected	<i>i</i> - 5	₩ Ann	ех А									
Olauses allected	'- '	7 (1111										
Other specs affected:	;	Т	est spe	re specification ecification ecification	าร	s #						
Other comments	s:		R9R9R4	9 Alarm I Alarm IF	IRP Info	ormation ORBA S rmation	n Ser olutio Serv	vice: n Se ⁻ ice: 3	ent in: 32.111-2 V3 t: 32.111-3 V 32.111-2 V4.: CORBA Solut	'3.6.0 3.0 (2	(2001-12 002-03)	2)

Annex A (normative): IDL specification (file name "AlarmIRPConstDefs.idl")

```
module AlarmIRPConstDefs
...
   This block identifies the probable cause of a reported alarm.
   interface ProbableCause
      const short INDETERMINATE = 0;
      const short ALARM_INDICATION_SIGNAL = 1;
      const short CALL_SETUP_FAILURE = 2;
      const short DEGRADED_SIGNAL_M3100 = 3;
      const short FAR_END_RECEIVER_FAILURE = 4;
      const short FRAMING ERROR M3100 = 5;
      const short LOSS OF FRAME = 6;
      const short LOSS OF POINTER = 7;
      const short LOSS OF SIGNAL = 8;
      const short PAYLOAD TYPE MISMATCH = 9;
      const short TRANSMISSION_ERROR = 10;
      const short REMOTE_ALARM_INTERFACE = 11;
      const short EXCESSIVE_BIT_ERROR_RATE = 12;
      const short PATH_TRACE_MISMATCH = 13;
      const short UNAVAILABLE = 14;
      const short SIGNAL_LABEL_MISMATCH = 15;
      const short LOSS_OF_MULTI_FRAME = 16;
      const short BACK_PLANE_FAILURE = 51;
      const short DATA_SET_PROBLEM = 52;
      const short EQUIPMENT_IDENTIFIER_DUPLICATION = 53;
      const short EXTERNAL_DEVICE_PROBLEM = 54;
      const short LINE_CARD_PROBLEM = 55;
      const short MULTIPLEXER_PROBLEM_M3100 = 56;
      const short NE_IDENTIFIER_DUPLICATION = 57;
      const short POWER_PROBLEM_M3100 = 58;
      const short PROCESSOR_PROBLEM_M3100 = 59;
      const short PROTECTION_PATH_FAILURE = 60;
      const short RECEIVER_FAILURE_M3100 = 61;
      const short REPLACEABLE_UNIT_MISSING = 62;
      const short REPLACEABLE_UNIT_TYPE_MISMATCH = 63;
      const short SYNCHRONISATION_SOURCE_MISMATCH = 64;
      const short TERMINAL_PROBLEM = 65;
      const short TIMING_PROBLEM_M3100 = 66;
      const short TRANSMITTER_FAILURE_M3100 = 67;
      const short TRUNK_CARD_PROBLEM = 68;
      const short REPLACEABLE UNIT PROBLEM = 69;
      const short AIR COMPRESSOR FAILURE = 101;
      const short AIR_CONDITIONING_FAILURE = 102;
      const short AIR_DRYER_FAILURE = 103;
      const short BATTERY_DISCHARGING = 104;
      const short BATTERY_FAILURE = 105;
      const short COMMERICAL_POWER_FAILURE = 106;
      const short COOLING_FAN_FAILURE = 107;
      const short ENGINE_FAILURE = 108;
```

```
const short FIRE DETECTOR FAILURE = 109;
const short FUSE_FAILURE = 110;
const short GENERATOR_FAILURE = 111;
const short LOW_BATTERY_THRESHOLD = 112;
const short PUMP_FAILURE_M3100 = 113;
const short RECTIFIER_FAILURE = 114;
const short RECTIFIER_HIGH_VOLTAGE = 115;
const short RECTIFIER_LOW_F_VOLTAGE = 116;
const short VENTILATION_SYSTEM_FAILURE = 117;
const short ENCLOSURE_DOOR_OPEN_M3100 = 118;
const short EXPLOSIVE_GAS = 119;
const short FIRE = 120;
const short FLOOD = 121;
const short HIGH_HUMIDITY = 122;
const short HIGH_TEMPERATURE = 123;
const short HIGH_WIND = 124;
const short ICE_BUILD_UP = 125;
const short INTRUSION DETECTION = 126;
const short LOW FUEL = 127;
const short LOW HUMIDITY = 128;
const short LOW CABLE PRESSURE = 129;
const short LOW TEMPERATURE = 130;
const short LOW_WATER = 131;
const short SMOKE = 132;
const short TOXIC_GAS = 133;
const short STORAGE_CAPACITY_PROBLEM_M3100 = 151;
const short MEMORY_MISMATCH = 152;
const short CORRUPT_DATA_M3100 = 153;
const short OUT_OF_CPU_CYCLES = 154;
const short SOFTWARE_ENVIRONMENT_PROBLEM = 155;
const short SOFTWARE_DOWNLOAD_FAILURE = 156;
const short ADAPTER_ERROR = 301;
const short APPLICATION_SUBSYSTEM_FAILURE = 302;
const short BANDWIDTH_REDUCTION = 303;
const short COMMUNICATION_PROTOCOL_ERROR = 305;
const short COMMUNICATION_SUBSYSTEM_FAILURE = 306;
const short CONFIGURATION_OR_CUSTOMIZING_ERROR = 307;
const short CONGESTION = 308;
const short CPU_CYCLES_LIMIT_EXCEEDED = 310;
const short DATA_SET_OR_MODEM_ERROR = 311;
const short DTE_DCE_INTERFACE_ERROR = 313;
const short EQUIPMENT_MALFUNCTION = 315;
const short EXCESSIVE_VIBRATION = 316;
const short FILE_ERROR = 317;
const short HEATING OR VENTILATION OR COOLING SYSTEM PROBLEM = 321;
const short HUMIDITY UNACCEPTABLE = 322;
const short INPUT OUTPUT DEVICE ERROR = 323;
const short INPUT DEVICE ERROR = 324;
const short LAN ERROR = 325;
const short LEAK DETECTION = 326;
const short LOCAL NODE TRANSMISSION ERROR = 327;
const short MATERIAL_SUPPLY_EXHAUSTED = 330;
const short OUT OF MEMORY = 332;
const short OUTPUT_DEVICE_ERROR = 333;
const short PERFORMANCE DEGRADED = 334;
const short PRESSURE UNACCEPTABLE = 336;
const short QUEUE_SIZE_EXCEEDED = 339;
const short RECEIVE_FAILURE = 340;
const short REMOTE_NODE_TRANSMISSION_ERROR = 342;
const short RESOURCE_AT_OR_NEARING_CAPACITY = 343;
const short RESPONSE_TIME_EXCESSIVE = 344;
const short RETRANSMISSION_RATE_EXCESSIVE = 345;
const short SOFTWARE_ERROR = 346;
```

```
const short SOFTWARE PROGRAM ABNORMALLY TERMINATED = 347;
const short SOFTWARE PROGRAM ERROR = 348;
const short TEMPERATURE_UNACCEPTABLE = 350;
const short THRESHOLD_CROSSED = 351;
const short TOXIC_LEAK_DETECTED = 353;
const short TRANSMIT_FAILURE = 354;
const short UNDERLYING_RESOURCE_UNAVAILABLE = 356;
const short VERSION_MISMATCH = 357;
const short A_BIS_TO_BTS_INTERFACE_FAILURE = 501;
const short A_BIS_TO_TRX_INTERFACE_FAILURE = 502;
const short ANTENNA_PROBLEM = 503;
const short BATTERY_BREAKDOWN = 504;
const short BATTERY_CHARGING_FAULT = 505;
const short CLOCK_SYNCHRONISATION_PROBLEM = 506;
const short COMBINER_PROBLEM = 507;
const short DISK_PROBLEM = 508;
const short EXCESSIVE_RECEIVER_TEMPERATURE = 510;
const short EXCESSIVE TRANSMITTER OUTPUT POWER = 511;
const short EXCESSIVE TRANSMITTER TEMPERATURE = 512;
const short FREQUENCY HOPPING DEGRADED = 513;
const short FREQUENCY HOPPING FAILURE = 514;
const short FREQUENCY REDEFINITION FAILED = 515;
const short LINE_INTERFACE_FAILURE = 516;
const short LINK_FAILURE = 517;
const short LOSS_OF_SYNCHRONISATION = 518;
const short LOST_REDUNDANCY = 519;
const short MAINS_BREAKDOWN_WITH_BATTERY_BACKUP = 520;
const short MAINS_BREAKDOWN_WITHOUT_BATTERY_BACKUP = 521;
const short POWER_SUPPLY_FAILURE = 522;
const short RECEIVER_ANTENNA_FAULT = 523;
const short RECEIVER_MULTICOUPLER_FAILURE = 525;
const short REDUCED_TRANSMITTER_OUTPUT_POWER = 526;
const short SIGNAL_QUALITY_EVALUATION_FAULT = 527;
const short TIMESLOT_HARDWARE_FAILURE = 528;
const short TRANSCEIVER_PROBLEM = 529;
const short TRANSCODER_PROBLEM = 530;
const short TRANSCODER_OR_RATE_ADAPTER_PROBLEM = 531;
const short TRANSMITTER_ANTENNA_FAILURE = 532;
const short TRANSMITTER_ANTENNA_NOT_ADJUSTED = 533;
const short TRANSMITTER_LOW_VOLTAGE_OR_CURRENT = 535;
const short TRANSMITTER_OFF_FREQUENCY = 536;
const short DATABASE_INCONSISTENCY = 537;
const short FILE_SYSTEM_CALL_UNSUCCESSFUL = 538;
const short INPUT_PARAMETER_OUT_OF_RANGE = 539;
const short INVALID PARAMETER = 540;
const short INVALID POINTER = 541;
const short MESSAGE NOT EXPECTED = 542;
const short MESSAGE NOT INITIALISED = 543;
const short MESSAGE OUT OF SEQUENCE = 544;
const short SYSTEM CALL UNSUCCESSFUL = 545;
const short TIMEOUT EXPIRED = 546;
const short VARIABLE OUT OF RANGE = 547;
const short WATCH DOG TIMER EXPIRED = 548;
const short COOLING SYSTEM FAILURE = 549;
const short EXTERNAL EQUIPMENT FAILURE = 550;
const short EXTERNAL_POWER_SUPPLY_FAILURE = 551;
const short EXTERNAL_TRANSMISSION_DEVICE_FAILURE = 552;
const short REDUCED_ALARM_REPORTING = 561;
const short REDUCED_EVENT_REPORTING = 562;
const short RECUCED_LOGGING_CAPABILITY = 563;
const short SYSTEM_RESOURCES_OVERLOAD = 564;
const short BROADCAST_CHANNEL_FAILURE = 565;
const short CALL_ESTABLISHMENT_ERROR = 566;
```

```
const short INVALID_MESSAGE_RECEIVED = 567;
const short INVALID_MSU_RECEIVED = 568;
const short LAPD_LINK_PROTOCOL_FAILURE = 569;
const short LOCAL_ALARM_INDICATION = 570;
const short REMOTE_ALARM_INDICATION = 571;
const short ROUTING_FAILURE = 572;
const short SS7_PROTOCOL_FAILURE = 573;
const short TRANSMISSION_FAILURE = 574;
};
```

•••