

Source : RAN WG1 Chairman

Object: R99 Cover Sheet: Out-of-synch handling (FDD+TDD)

The following item is proposed to be still included in Release -99.

Release 1999 Submission form

Work Area / Item:		Out-of-synch handling			
Affects:	UE/MS: X	CN:	UTRAN: X	Compatibility Issues:	Yes: No:X
Expected Completion Date:		3/2000			
Services impacted:		Not a service dependent feature			
Specifications affected:		25.214 & 25.224			
Tasks within work which are not complete:			The behaviour of UE (FDD) when downlink is detected out of synch needs some refinements and is not currently specified at all for TDD UE. The Node B needs to provide at least out-of-synch indication to higher layers, whether something else needs to be defined for UTRAN is not clear.		
Consequences if not included in Release 1999:			Essential to release -99 to define UE behaviour in problem situation		
Accepted by TSG#		for late inclusion in Release 1999:			