TSGW3#1(99)064

Agenda Item: 8.2

Source: Alcatel

Title: **Hard Handover and SRNS relocation inconsistencies in UMTS ZZ.02**

Document for:

_____

Hard Handover and SRNS relocation inconsistencies in UMTS ZZ.02

1   Introduction

In section 7.2.15.2 of UMTS ZZ.02 [1], there is an inconsistency between the drawing and the text: the drawing shows that the Iu user plane is set up before the target RNC sends SRNC Relcoation Proceeding 1, but the text tells the opposite (5/6).

In section 7.2.16.2 of UMTS ZZ.02, the message Hard Handover Proceeding 2 sent from the CN to the Serving RNC should be the same as the message Hard Handover Command of the section 7.2.16.1.

This contribution proposes following modifications to the referred section.

2   Proposed modifications to UMTS ZZ.02

2.1   Section 7.2.15.2

It is proposed to keep the text as it is and to modify the figure 16 in a way that shows the User Plane Set-up before the transmission of SRNC Relocation Proceeding 1 message.

2.2   Section 7.1.16.2

It is proposed to rename the message "Hard Handover Proceeding 2" into "Hard Handover Command". This leads to better harmonisation with the GSM.

3   References

[1]   UMTS ZZ.02 V0.1.0; UTRAN Functions, Examples on Signalling Procedures