CR-Form-v7

CHANGE REQUEST

⌘	**34.123-3 CR**	⌘**rev**	**-**	⌘ Current version:	**3.3.0**	⌘

*For **HELP** on using this form, see bottom of this page or look at the pop-up text over the ⌘ symbols.*

Proposed change affects: UICC apps⌘ ☐   ME **X** Radio Access Network ☐   Core Network ☐

Title: ⌘	CR for correction of two SM TCs to be consistent with 34.123-1
Source: ⌘	Anite Telecoms

Work item code: ⌘	N/A		***Date:*** ⌘	11/12/2003

Category: ⌘	**F**	***Release:*** ⌘	R99

Use one of the following categories:
F *(correction)*
A *(corresponds to a correction in an earlier release)*
B *(addition of feature),*
C *(functional modification of feature)*
D *(editorial modification)*
Detailed explanations of the above categories can
be found in 3GPP TR 21.900.

Use one of the following releases:
2   *(GSM Phase 2)*
R96   *(Release 1996)*
R97   *(Release 1997)*
R98   *(Release 1998)*
R99   *(Release 1999)*
Rel-4   *(Release 4)*
Rel-5   *(Release 5)*
Rel-6   *(Release 6)*

Reason for change: ⌘	1. The sequences for TCs 11.3.1 and 11.3.2 as currently implemented in 34-123-3 V3.3.0 are not consistent with 34.123-1 V5.5.0.
	The test step lt_timeoutOrReceiveDetachReq is not required in these test cases.
	Note: T1-031709 modifies the applicability statement for these test cases in TS 34.123-2 . The new applicability statement for these test cases states that they should only be applied to UEs supporting the "automatic PS attach procedure at switch on".

Summary of change: ⌘	1. TC_11_3_1:
	1) Remove lt_timeoutOrReceiveDetachReq
	2) Replace line 21 with a statement to Start t_3390
	3) Insert a new line after line 21 to wait for t_3390 to timeout
	2. TC_11_3_2:
	1. Remove lt_timeoutOrReceiveDetachReq
	2. Remove old line 22
	3. Correct indentation level for new lines 22-27

Consequences if not approved:	⌘ The TTCN for 11.3.1 and 11.3.2 will be not in line with 34.123-1.

Clauses affected:	⌘	N/A			

		Y	**N**			
Other specs affected:	⌘			Other core specifications	⌘	
				Test specifications		
				O&M Specifications		

Other comments:	⌘	Dependent upon T1-031696 and T1-031709

How to create CRs using this form:

Comprehensive information and tips about how to create CRs can be found at http://www.3gpp.org/specs/CR.htm. Below is a brief summary:

1) Fill out the above form. The symbols above marked ⌘ contain pop-up help information about the field that they are closest to.

2) Obtain the latest version for the release of the specification to which the change is proposed. Use the MS Word "revision marks" feature (also known as "track changes") when making the changes. All 3GPP specifications can be downloaded from the 3GPP server under ftp://ftp.3gpp.org/specs/ For the latest version, look for the directory name with the latest date e.g. 2001-03 contains the specifications resulting from the March 2001 TSG meetings.

3) With "track changes" disabled, paste the entire CR form (use CTRL-A to select it) into the specification just in front of the clause containing the first piece of changed text. Delete those parts of the specification which are not relevant to the change request.

Test Case Id	tc_11_3_1
Reason for change	The test step lt_timeoutOrReceiveDetachReq is not required and does not match TS 34.123-1.
Summary of change	• Remove lt_timeoutOrReceiveDetachReq • Replace line 21 with a statement to Start t_3390 • Insert a new line after line 21 to wait for t_3390 to timeout
Source of change	new change

Before:

After:

15		+ts_GMM_ServiceRequest(tsc_CellA)			Wait for GMM Attach from the UE. and authentication and ciphering
16		+ts_ActivatePDP_AcceptMO(tsc_CellA)			step 6,7,8 of the test procedure
17		+ts_AT_DeactPDP_Context			Originate Deactivate PDP Context Request using AT Commands
18		Dc ? RRC_DataInd (tcv_DeactPDP_ContextReq := RRC_DataInd.msg, tcv_TI_R := tcv_DeactPDP_ContextReq.ti)	car_PS_UplinkDirectTransfer (tsc_CellDedicated, tsc_RB3, cbr_Deact_PDP_ContextReq_MO(tsc_RejCau_Prot_Err))		Receive Deactivate PDP COntext from UE
19		+ts_SetTI_Rep(tcv_DeactPDP_ContextReq.ti)			Set the TI value
20		Dc ! RRC_DataReq	cs_PS_DataReq(tsc_CellDedicated , tsc_RB3, cbs_Deact_PDP_ContextAcp_MT(tcv_TI_S))		Send Deactivate PDP Context Accept
21		START t_3398			Step 7 in 34.123-1
22	TBP1	? TIMEOUT t_3398		(P)	
23		(tcv_CellInfoA.dl_DPCH_2ndScrCode := tsc_DL_DPCH_ScrC_3)			
24		+ts_RRC_RB_Rel(tsc_CellA)			RAB Release
25		+ts_SM_SetLLC_SAPI			Set the value of LLC SAPI
26		Dc ! RRC_DataReq	cs_PS_DataReq(tsc_CellDedicated , tsc_RB3, cbs_Modify_PDP_ContextReq_MT(tcv_TI_S, tcv_LLC_SAPI_x, cs_QoS_InteractiveOrBackgroundMT_left(tcv_DlyClass,tcv_TrafficClass)))		Send Modify PDP Context Request
27		Dc ? RRC_DataInd	car_PS_UplinkDirectTransfer (tsc_CellDedicated, tsc_RB3, cbr_SM_StatusMO(cbr_SM_Cause_v('51'O)))	(P)	As the context is not active, UE should respond with SM Status message.
28	TBE	(tcv_TestBody := FALSE)			

Detailed Comment:

Test Case Id	tc_11_3_2
Reason for change	The test step lt_timeoutOrReceiveDetachReq is not required and does not match TS 34.123-1
Summary of change	• Remove lt_timeoutOrReceiveDetachReq • Remove old line 22 • Correct indentation level for new lines 22-27
Source of change	new change

Before:

After:

		tt_TestBody			
11	TBS	(tcv_TestBody := TRUE)			
12		+ts_InitialiseDlyAndTrafficClass			
13		+ts_AT_OrgPS_Call(tsc_CellA)			Originate a PDP Context Request using AT commands
14		+ ts_RRC_ConnEst (tsc_CellA, ast_M0, originatingInteractiveCall)			Establish RRC Connect
15		+ts_GMM_ServiceRequest(tsc_CellA)			Wait for GMM Attach from the UE. and authentication and ciphering
16		+ts_ActivatePDP_AcceptM0 (tsc_CellA)			step 6,7,8 of the test procedure
17		D: ! RRC_DataReq	cs_PS_DataReq(tsc_CellDedicated , tsc_RB0, cs_DeactPDP_ContextReqMT(tcv_TI_8, tsc_RejCau_Prot_Err())		step 1
18		START t_3395			
19	TBF1	?TIMEOUT t_3395		(F)	
20	TBE1	(tcv_TestBody := FALSE)			
21	TBP1	D: ? RRC_DataInd	car_PS_UplinkDirectTransfer (tsc_CellDedicated, tsc_RB3, cr_DeactPDP_ContextAcpM0)	(P)	step 2
		CANCEL t_3395			
22		(tcv_CellInfoA.dl_DPCH_InitScrCode := tsc_DL_DPCH_ScrC_3)			
23		+ts_SM_SetLLC_SAPI			Set the value of LLC SAPI
24		+ts_RRC_RB_Rel(tsc_CellA)			Release the RAB
25		D: ! RRC_DataReq	cs_PS_DataReq(tsc_CellDedicated , tsc_RB3, cbs_Modify_PDP_ContextReq_MT(tcv_TI_8, tcv_LLC_SAPI_v, cs_QoS_InteractiveOrBackgroundMT_Ivt(tcv_DlyClass, tcv_TrafficClass)()		Send Modify PDP Context Request
26	TBP2	D: ? RRC_DataInd	car_PS_UplinkDirectTransfer (tsc_CellDedicated, tsc_RB3, cbr_SM_StatusM0(cbr_SM_Cause_v('51'O)()	(P)	As the context is not active, UE should respond with SM Status message
27	TBE2	(tcv_TestBody := FALSE)			

Detailed Comment	