Activating DCI for
type-2 CG-PUSCH
SRI = 0 which is asso-
ciated with PL-RS 0
CG-PUSCH
(PL-RS 0)
MAC CE update PL-RS and
SRI association
(SRI 0 is mapped to PL-RS 1)
CG-PUSCH
(PL-RS 0 or PL-RS 1?)
Time