Tx UE 1 and Tx UE 2 use adjacent REs for SL-PRS transmissions.

Tx UE 2's signal causes a near-far problem due to IBE, which interferes with Tx UE 1's signal at Rx UE.