

Report on test step RRC_M problems - v150

25/11/2002 17:18:17

page 1 of 1

Nr. of error report	Test step name	Version	Problem	Comment from MCC Task 160	Done date
020039	ts_SS_SetConfigRRC_RB3	v1.5.0	Configurations with DTCH shall be treated as well (for test cases tc_8_1_1_7, tc_8_1_1_8)	Accepted - v151	17/10/2002
020043	ts_C1_CheckIdleMode	v1.5.0	The Paging Response or Service request should ne received on the Dc Pco instead of AM. The purpose of this step is not to check Init Direct Transfer.	Accepted - v151	28/10/2002
	ts_GotoState6_1_Or6_3_MO	v1.5.0	The CM Service request and the service request messages are received twice.	Accepted - v151	28/10/2002

This report contains:

Number of problems: 3

Completed problems: 3