

Report on test step NAS problems - v120

produced on: 02/05/2002 12:50:15
page 1 of 1

Nr. of error report	Test step name	Version	Problem	Comment from MCC Task 160	Done date
020019	ts_AT_DTMF_StartTone	v1.2.0	According to 27.007, the AT command +VTS is optional.	Accepted - v130 - a PIXIT will be used to indicate if the AT command +VTS is supported. If not, an MMI command will be used.	16/04/2002

This report contains:

Number of problems: 1

Completed problems: 1