

Report on test step L3M problems - v106

produced on: 22/01/2002 10:52:44
page 1 of 1

Nr. of error report	Test step name	Version	Problem	Comment from MCC Task 160	Done date
010007					
	ts_GMM_ServReqAcpDef	v1.0.6	Should contain a reception of SERVICE REQUEST message on Dc PCO?	Accepted - v111	06/12/2001
	ts_GMM_ServReqAcpDef	v1.0.6	Test step should receive a SERVICE REQUEST message from UE and NOT issue a SERVICE ACCEPT! ts_GMM_ServiceRequest should be used here ?	Accepted - v111	06/12/2001

This report contains:

Number of problems: 2

Completed problems: 2